NEW YORK STATE RELIABILITY COUNCIL EC #312 – Friday April 11, 2025

Status Report: Under Frequency Load Shed WG

• Next Steps

- Continued discussion with the NYISO Planning Coordinator & NPCC regarding the once-in-five- year load shed studies as currently required by NERC and NPCC criteria
 - Need to determine if this frequency is adequate
- Need written summaries of the Transmission Owners descriptions of the once-per-year modifications to their UFLS
 - Underway
- Need written summary of the NYISO Reliability Coordinator review of annual submissions from Transmission Owners as currently required by NERC and NPCC criteria.
 - Underway
- Develop a draft paper describing the information gathered and a recommendation(s) for RRS and NYSRC EC consideration

• Next Meeting UFLS WG

o TBD